

Movie/Pay TV/VOD

Manufacturer	Model	DMM	Lodging Link II BIOS v 2.1	Lodging Link III	Lodging Link PTS
2M Electronic A/S	ASIS	515			
2M Electronic A/S	Eclipse	515			
2M Electronic A/S	EyeCom (2M version)	515			
2M Electronic A/S	MegASIS	515			
2M Electronic A/S	MMC (Locatel)	515			
2M Electronic A/S	Nice	515			
2M Electronic A/S	Roombase	515			
2M Electronic A/S	Telenor	515			
Dalvi Technology Ltd	Choice 24-7	541			

*Please Note: This is a UHLL Protocol Compliant Interface. Please make sure the installer loads the UHLL Protocol at setup time. If you have any questions, please write to hpdsupport@comtrol.com

Eona	Digital Entertainment System v1.50 (Serial Version)	556			
------	---	-----	--	--	--

UPDATED! *Please Note, this interface is the serial version and supports checksum and ACK/NAK. This device supports Movie Access Restrictions. Movie Access Restrictions are supported in UHLL using the UHLL Shell OCX version 3.2 or higher. [For OCX download page, click here](#) Additionally, this interface supports Guest Name Change and Guest Message Text Online. To make use of this feature, you will need to install [OCX version 3.8 or higher](#).

Eona	Digital Entertainment System v1.50 (TCP/IP Version)	555			
------	---	-----	--	--	--

UPDATED! *Please Note, this interface is the TCP/IP version and does not support checksum and ACK/NAK. This device supports Movie Access Restrictions. Movie Access Restrictions are supported in

Ordering Information
For purchasing information, contact your [Control Sales Representative](#)
Product Information
[Lodging Link III](#)
[Lodging Link PTS](#)
Technical Papers
[What is UHLL?](#)
In-depth explanation of how [LodgingLink works](#)
Developer Kits
[PMS](#)
[Developer Kit GSS](#)
[Developer Kit Partners](#)
[Property Management System Partners](#)
[Guest Service System Partners](#)

UHLL using the UHLL Shell OCX version 3.2 or higher. For OCX download page, click here. Additionally, this interface supports Guest Name Change and Guest Message Text Online. To make use of this feature, you will need to install OCX version 3.8 or higher.

ETV Interactive Ltd	ETVi	583			
---------------------	------	-----	--	--	--

*Please Note: This is a UHLL Protocol Compliant Interface. Please make sure the installer loads the UHLL Protocol at setup time. If you have any questions, please write to hpdsupport@comtrol.com. This device supports many new features of the UHLL Addendum Specification. Please consult the newest version of the spec as well as our OCX downloads page.

GalaVu Entertainment Inc.	All	564			
---------------------------	-----	-----	--	--	--

General Dynamics Interactive	Intrigue Version 8.0	585			
------------------------------	----------------------	-----	--	--	--

*Please Note: This is a UHLL Protocol Compliant Interface. Please make sure the installer loads the UHLL Protocol at setup time. If you have any questions, please write to hpdsupport@comtrol.com

Granda Systems	Ascari Version 6.01	570			
----------------	---------------------	-----	--	--	--

Insystcom	Sealynx 3.0	540			
-----------	-------------	-----	--	--	--

This device also supports email, internet, folio view, checkout, room service, content delivery and business services *Please Note: This is a UHLL Protocol Compliant Interface. Please make sure the installer loads the UHLL Protocol at setup time. If you have any questions, please write to hpdsupport@comtrol.com

KoolConnect Technologies, Inc	Intrigue Version 8.0	585			
-------------------------------	----------------------	-----	--	--	--

*Please Note: This is a UHLL Protocol Compliant Interface. Please make sure the installer loads the UHLL Protocol at setup time. If you have any questions, please write to hpdsupport@comtrol.com

Locatel Group	Eclipse	515			
---------------	---------	-----	--	--	--

Lodgenet	BOI (Billing Only)	544			
----------	--------------------	-----	--	--	--

UPDATED! This interface now supports Resync functionality. To make use of this feature, you will need to install OCX version 3.41 or higher.

Lodgenet	BOI+ (BIO with Folio View)	544			
----------	----------------------------	-----	--	--	--

UPDATED! This interface now supports Resync functionality. To make use of this feature, you will need to install OCX version 3.41 or higher.

Lodgenet	Post By Station Number	546			
----------	------------------------	-----	--	--	--

UPDATED! This interface now supports Resync functionality. To make use of this feature, you will need to install **OCX version 3.41 or higher**.

Lodgenet	VCO (BOI+ with X-Checkout)	544			
----------	----------------------------	-----	--	--	--

UPDATED! This interface now supports Resync functionality. To make use of this feature, you will need to install **OCX version 3.41 or higher**.

Media Entertainment Networks	Pay Video Systems	590			
------------------------------	-------------------	-----	--	--	--

Miracle TV Corp	Cibertron - MiTV Communications Server 1.1	587			
-----------------	--	-----	--	--	--

*Please Note: This is a UHLL Protocol Compliant Interface. Please make sure the installer loads the UHLL Protocol at setup time. If you have any questions, please write to hpdsupport@comtrol.com

NEOS Interactive Ltd.	Version 4.0	575			
-----------------------	-------------	-----	--	--	--

Network Connection Inc.	InnView	580			
-------------------------	---------	-----	--	--	--

NXTV	Application Server NXTVue25	542			
------	-----------------------------	-----	--	--	--

*Please Note: This is a UHLL Protocol Compliant Interface. Please make sure the installer loads the UHLL Protocol at setup time. If you have any questions, please write to hpdsupport@comtrol.com

OnCommand	Marriott CFRC	513			
-----------	---------------	-----	--	--	--

OnCommand	Multi-threaded	511			
-----------	----------------	-----	--	--	--

OnCommand	Multi-Threaded Via Station Number	510			
-----------	-----------------------------------	-----	--	--	--

OnCommand	OCX (WebTV)	511			
-----------	-------------	-----	--	--	--

OnCommand	OCX (WebTV) Via Station Number	510			
-----------	--------------------------------	-----	--	--	--

OnCommand	Simple	512			
-----------	--------	-----	--	--	--

Otrum Technology Ltd	Guestlink (Global)	560			
-------------------------	--------------------	-----	--	--	--

Requires OCX Version 3.2 or higher [For OCX download page, click here](#)

Otrum Technology Ltd	Syscom 2, Syscom 3, Syscom 4 and Syscom 2000	560			
-------------------------	--	-----	--	--	--

Requires OCX Version 3.2 or higher [For OCX download page, click here](#)

Quadriga (Formally Thorn)	Genesis	560			
------------------------------	---------	-----	--	--	--

Requires OCX Version 3.2 or higher [For OCX download page, click here](#)

Quadriga (Formally Thorn)	Pay TV System	560			
------------------------------	---------------	-----	--	--	--

Requires OCX Version 3.2 or higher [For OCX download page, click here](#)

Roomster, Inc.	RoomsterDVOD	520			
----------------	--------------	-----	--	--	--

SeaChange International	GuestServe Hotel VOD (Video on Demand)	522			
----------------------------	--	-----	--	--	--

Smart Hospitality Corporation	nSTREAMS HMS	511			
----------------------------------	--------------	-----	--	--	--

Spectradyne	All	564			
-------------	-----	-----	--	--	--

Tech-Inter-Com	MediaChannel	550			
----------------	--------------	-----	--	--	--

Telesys	GuestNet	533			
---------	----------	-----	--	--	--

TELUS (Triple Crown)	All	564			
-------------------------	-----	-----	--	--	--




Time Warner	All	522			
-------------	-----	-----	--	--	--

Total Vision	ALL Version 1.0	543			
--------------	-----------------	-----	---	---	---




*Please Note: This is a UHLL Protocol Compliant Interface. Please make sure the installer loads the UHLL Protocol at setup time. If you have any questions, please write to hpdsupport@control.com

VDA Multimedia	VDA HCS	595			
----------------	---------	-----	---	---	---

Requires OCX Version 3.2 or higher [For OCX download page, click here](#)

Western	Speedway 4.0 (Bi-Directional) Movie /Internet	552			
---------	---	-----	---	---	---

*Please Note: This is a UHLL Protocol Compliant Interface. Please make sure the installer loads the UHLL Protocol at setup time. If you have any questions, please write to hpdsupport@control.com

Western	SpeedWay TV (unidirectional posting only)	551			
---------	---	-----	---	---	---

*Please Note: This is a UHLL Protocol Compliant Interface. Please make sure the installer loads the UHLL Protocol at setup time. If you have any questions, please write to hpdsupport@control.com

49 Interfaces Supported